Printed on: 8/30/2009 7:32:19 PM

| | | | | | | 1 111110 | d 011 : 0/00/2000 7:02:10 1 |
|---|----------|-----------|-----------------|----------------|--------------|-------------|-----------------------------|
| National Transportation Safety Board | N | TSB ID: | ERA09WA2 | 41 | Aircraft Reg | istration N | umber: CP-1373 |
| FACTUAL REPORT | Od | ccurrence | e Date: 04/13 | 3/2009 | Most Critica | l Injury: F | atal |
| AVIATION | Od | ccurrence | Type: Accid | dent | Investigated | By: For | eign |
| Location/Time | | | | | | | |
| Nearest City/Place | State | Zip | Code | Local Time | Time Zone | | |
| Concepcion | | | | 2305 | UTC | | |
| Airport Proximity: Off Airport/Airstrip | Distance | From La | nding Facility: | | ' | | |
| Aircraft Information Summary | | | | | | | |
| Aircraft Manufacturer | | | Model/Serie | S | | | Type of Aircraft |
| CESSNA | | | 210/M | | | | Airplane |
| Revenue Sightseeing Flight: | | | Air I | Medical Transp | ort Flight: | | |

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On April 11, 2009, at 2305 universal coordinated time (1905 local time), a Cessna 210M, Bolivian registration CP-1373, was destroyed when it impacted terrain shortly after taking off from Concepcion Airport (SLCP), Concepcion, Bolivia. The certificated commercial pilot and three passengers, all Bolivian citizens, were fatally injured. Night visual meteorological conditions prevailed. The flight was operating on a visual flight rules flight plan from Concepcion to El Trompillo Airport (SLET), Santa Cruz, Bolivia. The medical evacuation flight was operating under Bolivian flight regulations.

The investigation is under the jurisdiction of the government of Bolivia. Further information may be obtained from:

Direccion General de Aeronautica Civil Autoridad Aeronautioca Civil Edificio Palacio De Comunicaciones Av. Mcal. Santa Cruz, No. 1278 4to Pisa La Paz, Bolivia

Tel: 591 (2) 2374142

http://www.dgac.gov.bo

This report is for informational purposes, and only contains information released by the government of Bolivia.

Updated on May 19 2009 1:44PM

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: ERA09WA241

Occurrence Date: 04/13/2009

| AVIATION | | Occurre | ence Type: | : Accident | | | | | | | |
|---------------------------------------|--------------------|----------|-----------------|---------------------|---------|----------------|------------------------|----------------|---------------|--------|----------|
| Landing Facility/Approach In | formation | | | | | | | | | | |
| Airport Name | | Ai | rport ID: | Airport Elevation | Run | way Used | Runwa | y Lengt | h | Runw | ay Width |
| Concepcion | | s | LCP | Ft. MS | _ N/A | 4 | | | | | |
| Runway Surface Type: | | | | | | | | | | | |
| Runway Surface Condition: | | | | | | | | | | | |
| Approach/Arrival Flown: NONE | Ē | | | | | | | | | | |
| VFR Approach/Landing: None | | | | | | | | | | | |
| Aircraft Information | | | | | | | | | | | |
| Aircraft Manufacturer CESSNA | | | Model/ 210/N | /Series <i>M</i> | | | | Serial 2106 | Numbe 2086 | er | |
| Airworthiness Certificate(s): Norm | ıal | | • | | | | | • | | | |
| Landing Gear Type: Retractable | - Tricycle | | | | | | | | | | |
| Amateur Built Acft? No | Number of Seats: 6 | 6 | Certifie | d Max Gross Wt. | | 3800 | LBS | Numbe | r of En | gines: | 1 |
| Engine Type: | | E | Engine Ma | inufacturer: | | Model/Se | Model/Series: | | | Rate | d Power: |
| - Aircraft Inspection Information | | | | | | • | | | | | |
| Type of Last Inspection | | D | ate of Las | t Inspection | Time Si | nce Last Inspe | Inspection Hours | | | ne Tot | al Time |
| Annual | | (| 04/2009 | | | | Hours | | | | Hours |
| - Emergency Locator Transmitter (| ELT) Information | | | | | | | | | | |
| ELT Installed?/Type | | E | LT Opera | ted? | ELT Aid | ded in Locatin | Locating Accident Site | | | | |
| Owner/Operator Information | | | | | | | | | | | |
| Registered Aircraft Owner | | | Street A | Address | | | | | | | |
| | | | City | Santa Cruz | | | | | State | | Zip Code |
| Operator of Aircraft | | | Street A | ddress | | | | | • | | |
| | | | City | | | | | | | e | Zip Code |
| Operator Does Business As: | | | | | O | perator Desig | nator Co | de: | | | |
| - Type of U.S. Certificate(s) Held: 1 | None | | | | | | | | | | |
| Air Carrier Operating Certificate(s) | : | | | | | | | | | | |
| Operating Certificate: | | | | Operator Certif | cate: | | | | | | |
| Regulation Flight Conducted Unde | r: Non-U.S., Com | mercial | | • | | | | | | | |
| Type of Flight Operation Conducted | d: Non-scheduled: | ; Domest | ic; Passe | enger Only | | | | | | | |
| |] | FACTUA | AL REPO | RT - AVIATION | | | | | | | Page 2 |

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: ERA09WA241

Occurrence Date: 04/13/2009

| Z | | | L | | | . 0, _0 | | | | | | | | | | |
|------------------------------|--------------|---------------------|---------|---------------------------|-------------------------|---------|--------|----------|-----------|----------------|---------|------------|-------|------------|-----------|---------------------|
| AVIAT | ION | | | Occurrence | ce Type: Acc | cident | | | | | | | | | | |
| First Pilot Information | | | | | | | | | | | | | | | | |
| Name | | | | | | City | | | | | Sta | ate | Date | of Birth | | Age |
| On File | | | | | | | | | | | | | | | | 50 |
| Sex: M Seat Occupied | d: Left | | Occu | pational Pil | lot? Unkno | wn | | | | Cei | rtifica | te Numb | er: | | | |
| | nmercial | | | <u> </u> | | | | | | | | | | | | |
| Airplane Rating(s): | | | | | | | | | | | | | | | | |
| Rotorcraft/Glider/LTA: | | | | | | | | | | | | | | | | |
| Instrument Rating(s): | | | | | | | | | | | | | | | | |
| Instructor Rating(s): | | | | | | | | | | | | | | | | |
| Current Biennial Flight Revi | ew? | | | | | | | | | | | | | | | |
| Medical Cert.: | Medio | al Cert. S | tatus: | | | | | | D | ate of La | ast M | edical E | xam: | • | | |
| | | | | | | | | | | | | | | | | |
| - Flight Time Matrix | All A/C | This Make and Model | | Airplane Single Engine | Airplane Mult-Engine | Ni | ght | Actual | Instrumen | t Simulated | | Rotorcraft | | Glider | | Lighter Than Air |
| Total Time | | | \top | | | | | | Т | | 寸 | | 寸 | | \dagger | |
| Pilot In Command(PIC) | | | | | | | | | | | | | | | | |
| Instructor | | | | | | | | | | | | | | | | |
| Instruction Received | | | | | | | | | | | | | | | | |
| Last 90 Days | | | | | | | | | | | | | | | | |
| Last 30 Days | | | \perp | | | | | | | | | | | | | |
| Last 24 Hours | <u> </u> | | | | | | | | | | | | | | | |
| Seatbelt Used? Unknown | Sho | ulder Harr | ness U | Jsed? Unkı | nown | | Toxico | ology Pe | forme | d? | | Se | econo | d Pilot? N | lо | |
| Flight Plan/Itinerary | | | | | | | | | | | | | | | | |
| Type of Flight Plan Filed: V | FR | | | | | | | | | | | | | | | |
| Departure Point | | | | | | | State | | Airport | Identifie | er | Depar | ture | Time | Ti | me Zone |
| Same as Accident/Incide | ent Location | า | | | | | | | SLCP | | | , | | | U | TC |
| Destination | | | | | | | State | | Airport | Identifie | er | | | | | |
| Santa Cruz | | | | | | | | | SLET | | | | | | | |
| Type of Clearance: None | | | | | | | | • | | | | | | | | |
| Type of Airspace: | | | | | | | | | | | | | | | | |
| Weather Information | | | | | | | | | | | | | | | | |
| Source of Wx Information: | | | | | | | | | | | | | | | | |
| Unkno | own | | | | | | | | | | | | | | | |
| | | | F | FACTUAL | REPORT - | - AVI | ATION | N | | | | | | | | Page 3 |

National Transportation Safety Board FACTUAL REPORT

NTSB ID: ERA09WA241

Occurrence Date: 04/13/2009

| | Accident Site Deg. Mag. "Hg |
|---|-------------------------------|
| Sky/Lowest Cloud Condition: Ft. AGL Ft. AGL Condition of Light: Night Lowest Ceiling: Temperature: °C Dew Point: °C Weather Conditions at Accident Site: Visual Conditions Wind Direction: Wind Speed: Wind Gusts: Visibility (RVR): Ft. Visibility (RVV) SM Precip and/or Obscuration: | Deg. Mag. |
| Sky/Lowest Cloud Condition: Ft. AGL Ft. AGL Condition of Light: Night Lowest Ceiling: Temperature: °C Dew Point: °C Weather Conditions at Accident Site: Visual Conditions Wind Direction: Wind Speed: Wind Gusts: Visibility (RVR): Ft. Visibility (RVV) SM Precip and/or Obscuration: | Deg. Mag. |
| Sky/Lowest Cloud Condition: Ft. AGL Condition of Light: Night Lowest Ceiling: Ft. AGL Visibility: SM Altimeter: Temperature: °C Dew Point: Wind Speed: Wind Gusts: Visibility (RVR): Ft. Visibility (RVV) SM Precip and/or Obscuration: | |
| Sky/Lowest Cloud Condition: Ft. AGL Condition of Light: Night Lowest Ceiling: Ft. AGL Visibility: SM Altimeter: Temperature: °C Dew Point: Wind Speed: Wind Gusts: Visibility (RVR): Ft. Visibility (RVV) SM Precip and/or Obscuration: | |
| Temperature: °C Dew Point: °C Weather Conditions at Accident Site: Visual Conditions Wind Direction: Wind Speed: Wind Gusts: Visibility (RVR): Ft. Visibility (RVV) SM Precip and/or Obscuration: | "Hg |
| Temperature: °C Dew Point: °C Weather Conditions at Accident Site: Visual Conditions Wind Direction: Wind Speed: Wind Gusts: Visibility (RVR): Ft. Visibility (RVV) SM Precip and/or Obscuration: | |
| Wind Direction: Visibility (RVR): Ft. Visibility (RVV) SM Precip and/or Obscuration: | |
| Precip and/or Obscuration: | |
| | |
| Accident Information | |
| Aircraft Damage: Destroyed Aircraft Fire: Unknown Aircraft Explosion Unknown | |
| | |
| - Injury Summary Matrix Fatal Serious Minor None TOTAL | |
| First Pilot 1 1 | |
| Second Pilot | |
| Student Pilot | |
| Flight Instructor | |
| Check Pilot | |
| Flight Engineer | |
| Cabin Attendants | |
| Other Crew | |
| Passengers 3 3 | |
| - TOTAL ABOARD - 4 4 | |
| Other Ground | |
| - GRAND TOTAL - 4 4 | |

National Transportation Safety Board

NTSB ID: ERA09WA241

| FACTUAL REPORT | Occurrence Date: 04/13/2009 |
|--|-----------------------------|
| AVIATION | Occurrence Type: Accident |
| Administrative Information | _1 |
| Investigator-In-Charge (IIC) | |
| Paul R. Cox | |
| Additional Persons Participating in This Accident/Incident | dent Investigation: |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |